








*** Thank you for purchasing this quality product. Be sure to check all packing materials carefully for small parts which may have come loose inside the carton during shipment. Identify and count all parts and compare with parts list below.

*** Assemble product on a flat, soft surface such as a carpet or cloth to prevent scratching the finish. Read all instruction and study the drawings carefully before starting the assembly process.








IMPORTANT: Do not tighten bolts completely until all bolts are completely lined up and inserted into holes

PARTS LIST











NO.	DIAGRAM	PART NAME	Q'Ty
1		Front Leg Frame	1 pc
2		Back Leg Frame	1 pc
3		Upper Stretcher	2 pcs
4		Lower Stretcher	2 pcs
5		Desk Top	1 pc
6		Hutch	1 pc

HARDWARE LIST


NO.	DIAGRAM	PART NAME	Q'Ty
A		Bolt 6.3 x 15 (mm)	16 pcs
B		Screw: 4 x 40 (mm)	16 pcs
C		Screw: 4 x 20 (mm)	6 pcs
D		Allen Key (M4)	1 pc




#36142 & 36143 is packed in 2 cases

Carton	Disignation	Part		Hardware
Item: #36142	Front Leg Frame x 1pc	#1		 A : Bolt x 16pcs
	Back Leg Frame x 1pc	#2		 B :Screw 40 x 16pcs
	Upper Stretcher x2pcs	#3		 C : Screw 20 x 6pcs
	Lower Stretcher x2pcs	#4		 D : Allen Key x 1pc
	Desk Top x1pc	#5		
Item: #36143	Hutch x 1pc	#6		


STEP 1: LEG FRAME ASSEMBLY




STEP 2: LEG FRAME ASSEMBLY




STEP 3: LEG FRAME - COMPUTER DESK ASSEMBLY


B  16 pcs




STEP 4: LEG FRAME - COMPUTER DESK - UPPER DESK ASSEMBLY



STEP 5: LEG FRAME - COMPUTER DESK - UPPER DESK ASSEMBLY



STEP 6:



ASSEMBLY IS COMPLETED