



ASSEMBLY INSTRUCTIONS

Model number:G5142-09/G5142-12/G5142-03/G5142-01 Chair





STEP 1



STEP 2



G5142-09/-12/-03/-01HDWR


A		1PC	M6*15
B		5PCS	φ8*16
C		1PC	4mm
D		4PCS	M6*40







Please Contact us if you are Missing
Parts or have any Questions
877-364-8464
info@sunsettrading.com



Please Contact us if you are Missing
 Parts or have any Questions
877-364-8464
info@sunsettrading.com



		Part Description	Quantity
G5142-09	1		1
G5142-12	2		1
G5142-03	3		1
G5142-01	4	 (Φ16*15)	4
	HDWR	HDWR PACK	1